

**Circular Pitch Hobs**

st number of starts

<b><u>14 1/2 PA</u></b>	<b><u>20 PA</u></b>	<b><u>22 1/2 PA</u></b>	pregrind	<b><u>2st 14 1/2PA</u></b>	<b><u>2st 20PA</u></b>
1/16	1/8	3/8	<b><u>20 PA</u></b>	0.3057	21/32
1/8	3/16			0.31416	3/4
3/16	1/4	<b><u>25 PA</u></b>	3/4	1/2	31/32
1/4	5/16		13/16	3/4	
5/16	1/2	0.4147	15/16		<b><u>3st 20PA</u></b>
3/8	0.6			<b><u>3st 14 1/2PA</u></b>	
7/16	5/8	<b><u>30 PA</u></b>	<b><u>30 PA</u></b>		1.0996
1/2	11/16			1/4	
9/16	3/4	2.5mm	0.5302	5/16	<b><u>4st 20PA</u></b>
5/8	13/16	0.666		1	
11/16	7/8				1/4
3/4	1 1/4			<b><u>4st 14 1/2PA</u></b>	
13/16	2 1/4				<b><u>5st 20PA</u></b>
1	3			1/4	
1 1/8				3/8	0.5341
1 3/8	0.100				
1 1/2	0.3452			<b><u>6st 14 1/2PA</u></b>	<b><u>6st 20PA</u></b>
1 9/16	0.4348				
1 3/4	0.938			1/4	0.45
	1.080				
0.05					<b><u>9st 20PA</u></b>
0.075					
0.115					5/16
0.4					
0.5072					<b><u>4st 25PA</u></b>
0.6					
					0.1111
<b><u>15 PA</u></b>					
1/4					
<b><u>19dg55 PA</u></b>					
0.3145					